

Coal Mining Locations



Areas of Geologic Conditions
Relating to Occurrence of Coal




Areas of Geologic Conditions
Relating to Occurrence of Lignite



Permitted Coal Mine



Reclamation Only



1. Sandow – Alcoa Inc. [R]
2. Big Brown – Luminant Mining Co.
3. Martin Lake – Luminant
4. Thermo – Luminant
5. Rachal – Farco Mining Inc. [R]
6. San Miguel – San Miguel Electric Cooperative Inc.
7. Gibbons Creek – Texas Municipal Power Agency [R]
8. Calvert – Walnut Creek Mining Co.
9. Darco – Norit Americas Inc. [R]
10. Jewett – Texas Westmoreland Coal Co.
11. South Hallsville – Sabine Mining Co.
12. Monticello Winfield – Luminant
13. Palafox – Farco Mining Inc. [R]
14. Eagle Pass – Dos Repùblicas Resources Co. Inc.
15. Treviño – Farco [R]
16. Oak Hill – Luminant
17. Three Oaks – Alcoa
18. Twin Oak – Luminant
19. Kosse – Luminant
20. Leesburg – Luminant

© Texas Almanac

Based on a map of the Railroad Commission of Texas.